

NuMI-MINOS status report





Detectors

Far Detector:

▶ 99.5% uptime, no issues.


Near Detector:

- ▶ 64.7% uptime.
- Down on Wed for DAQ computer replacement and LCW heat exchanger flush
- On turn-on, water leak killed coil PS
- Replacement just finished, but to overlap downtimes also doing:
 - ⇒ Welding on detector face to install Ar vent for T962
 - ⇒ Installation of second LCW heat exchanger to compensate for warmer sump water
 - ⇒ Work finishes tomorrow, detector up Wednesday.





Protons




- \triangleright 5.5 × 10¹⁸ protons each week
- Real gains from 11-batch slip-stacking
- Improvement is around 10% vs best before the long shutdown
- Good weeks in spite of downtime


Target Hall:

- Will access in Wednesday scheduled downtime
 - ⇒ Turn down pressure on leaking Horn2 cooling line




In detail...






2 Weeks ending 00:00 Monday 28 January 2008



Consistently running 7 booster turns in 11-batch mode



Protons



 \triangleright Exceeded 4×10^{20} integrated protons delivered